

Download Onan 5500 Marquis Gold Generator Repair Manual

This was an exact replacement for the original Onan/Cummins 149-2620 fuel pump. My original fuel pump developed the fairly common problem of causing the generator to stall after about 20 to 30 minutes then requiring a cool down before it would restart and run for another 20 to 30 minutes. This is a direct replacement if you refer to the Airtex Web site and get the right unit for your Onan generator. They make multiple units for the different electrical connections and fuel line configurations.